


by Schneider Electric

WIRING INSTRUCTIONS

No. 30TV75MS COAXIAL CABLE TV ANTENNA SOCKET

This socket is designed to accommodate solid core conductor coaxial cable with insulation (dielectric) to approximately 5mm diameter for solderless connections.



- 1. Strip off black outer casing 12mm from end of cable.
- Fold braid or aluminium foil back over outer casing. Strip off 6mm of exposed insulation (dielectric) leaving 6mm of centre conductor exposed.

ASSEMBLY DETAILS



Pass cable under cable clamp and locate centre conductor in terminal hole, secure cable and conductor by clamping with screws.

F219/03

CLIPCOM 21079